TIB's

✦TECHNOPEDIA✦

Doc. #	Description
12079	Pressure Solenoid (old TIB-79)
12078	Sensor Dust Cover (old TIB-78)
12077	Current ETR Issues (old TIB-77)
12076	Drum Related Problems (old TIB-76)
12075	Machine Stops In Cycle (old TIB-75)
12074	Connector Clips (old TIB-74)
12072	Master Wrinkle (old TIB-72)
12071	Copy Quality (old TIB-71)
12070	Paper Detection Sensor Receive (old TIB-70)
12069	Roll Pin Replacement (old TIB-69)
12068	Technical Tips (old TIB-68)
12067	RC Power Supply Units (old TIB-67)
12066	RC Circuit Boards (old TIB-66)
12065	RG Operation Panels (old TIB-65)
12062	Board Compat./Part # Changes (old TIB-62)
12064	RC Cutter Motor Rotates (old TIB-64)
12063	Disposal Spec./Recommendations (old TIB-63)
12061	System Rom Version (old TIB-61)
12060	Master Disposal Jams (old TIB-60)
12059	Wrinkled Masters (old TIB-59)
12058	Spacer Cushion / "O" Ring (old TIB-58)
12057	Tape Sorter Conversion A4/B4 (old TIB-57)
12056	Drum Body Cracking (old TIB-56)
12055	Drum Specifications/Adjustments (old TIB-55)
12054	Post Card/Envelope Attachment (old TIB-54)
12053	T3/Master Cut Malfunction (old TIB-53)
12052	Cutter Assembly (old TIB-52)
12051	IT I/O PCB Modification (old TIB-51)
12050	Drum PCB Cover (old TIB-50)
12049	Modification Of Drum PCB (old TIB-49)
12048	Write Roller (old TIB-48)
12047	A4/B4 Machines (old TIB-47)
12046	Fuse Panel (old TIB-46)
12037	Separator Spring; Rel Lever (old TIB-37)
12045	IT I/O PCB (old TIB-45)
12044	Vertical Black Dotted Lines (old TIB-44)
12043	Paper Sensors (old TIB-43)
12042	Separator ; Design Change (old TIB-42)
12041	Troubleshooting Ink System (old TIB-41)
12040	Starter Roller; Clamp Plate Base (old TIB-40)
12039	Pickup Roller Assembly (old TIB-39) 27K 04/18/89
12038	Troubleshooting New Style Drum PCB (old TIB-38)
12033	2500 Master Roll Brake Ass'y (old TIB-33)
12036	New Style Write Roller (old TIB-36)
12035	Master Holder (old TIB-35)
12034	Feed Roller; Stopper Cap (old TIB-34)
12032	2500 Upper Discharge Roller (old TIB-32)
12031	Sticker Sheet/Upper Discharge Roller (old TIB-31)